

DONNING (PUT ON)



1 Select appropriate product size and type that matches the protection level needed, then do a visual inspection for possible damage.



2 Sit in a clean designated area, remove shoes and empty pockets of items that may pose a safety risk.



3 Carefully don your suit without shoes and pull coverall over arms and shoulders with zip halfway up.



4 Don your RPE (respirator / mask), pull up your hood to ensure close fit to the face then zip up the coverall.



5 With preinstalled re-sealable adhesive tape, seal up storm flap to ensure zip is covered from possible ingress of dust / liquid.



6 Put on safety boots with coverall over the footwear and gloves to be worn over coverall sleeves (taped where necessary).

7 To ensure a smooth seal on taped areas, it may be easier to ask a dressing buddy to assist.

8 Do stretch exercises to ensure size suitability before entering workplace



DOFFING (TAKE OFF)

1 Upon decontamination, move to a clean area away from workplace hazards.

2 Carefully detach self-adhesive storm flap from the coverall and unzip to the waist.



3 Pull and invert hood away from your head.



4 With both arms crossed behind your back, release the first arm from coverall by grabbing the edge of the sleeve with the other hand. Then extract the second arm from within coverall by inverting the garment.



5 Roll the garment down the body and continue to invert the outside of the coverall towards the inside.



6 Roll coverall inside out into a bundle and dispose according to local regulations.



ATTENTION:
Make sure that no contaminant comes into contact with wearer